
BENETEAU CYCLADES 39.3

She was only used for charter between 2008 - 2009.

Specifications/Özellikler

Builder/Yapımcı	:	Beneteau	
Model/Model	:	Cyclades 39.3	
Year/Yapım yılı	:	2008	
Hull/Bordo	:	GRP	
Flag/Bayrak	:	TC	
Price/Fiyat	:	72.500 Euro	
VAT/Tax	:	Not paid	
Dimensions/Boyutlar	:	LOA/Tam Boy	– 11.70 metres
	:	Beam/Eni	– 3.90 metres
	:	Draft/Su Çekimi	– meters
	:	Displacement	– Tonnes
Speed/Hız	:	Top Speed/Maksimum hızı	– 7.5 Knots
	:	Cruising Speed/Seyir Hızı	– Knots

Machinery & Equipment/Makine ve Cihazlar

Main Engines/Motor Markası	:	Yanmar 40hp, diesel
Propeller Type/Pervane Tipi	:	Three blade
Propulsion System/Yürütme Sistemi	:	Shaft drive

Electrical/Elektrik Sistemi

Service Battery/Servis Akusu	:	3 x 180 Ah - new in 2018
Starter Battery/Mars Akusu	:	1 x 102 Ah - new in 2019
Battery Charger/Redresör	:	2 x 25 amp
Other/Diğer	:	Sony CD/MP3

Navigation/Navigasyon

Depth,Speed/Derinlik, Hız	:	Raymarine ST60+
Wind/ Ruzgar	:	
Autopilot/Otopilot	:	RaymarineST6002
Chartplotter/Harita Okuyucusu	:	Raymarine - replaced in 2015
Compass/Pusula	:	Plastimo
VHF	:	Raymarine RAY 54E

Tank Capacities/Tank Kapasitesi

Fuel/Dizel	:	220 Litres
Fresh Water/Tatlı Su	:	330 Litres
Black Water/Siyah Su	:	2 x 50 Litres

Rigging, Sails & Canvas/Donanım, Yelkenler & Tenteler

Sails/Yelkenler	:	Full battened main sail
	:	Furling genoa
Winches/Vinçler	:	2 x 32 Harken two speed
	:	2 x 40 Harken two speed
Canvas/Tenteler	:	Bimini and sprayhood

Accommodation/Konaklama

Salon	:	Salon table convertible to double bed
Cabins/Kabinler	:	Forward double cabin with own facilities-wc -elect.
	:	Two aft double cabins share bathroom- wc -elect.
Galley/Mutfak	:	Vitrifrigo refrigerator 180 ltr
	:	Two burner gas hob

Deck & Safety/Güverte ve Güvenlik

Windlass/Irgat	:	Quick electrical - maintained in 2019
Chain/	:	80m x 8mm chain with anchor
	:	Quick chain counter
Dinghy/Bot	:	2.40m
Life Raft/Can Salı	:	Cruiser 4 person
Outboard/Dıştantakma	:	2 hp Honda, 4 stroke
Gangway/Paserella	:	Aluminium

All information given by Typhoon Yachting is given in good faith and believed to be accurate. However, neither the company nor its individual employees can be held responsible for any inaccuracy in information received from owners or their representatives.

We therefore recommend that all particulars are checked beforehand and we further advise clients to undertake an independent survey by a suitably qualified marine surveyor.